

# VdS analysis of 25-year inspections of sprinkler system

Marcel Ruesink,  
Powered by Leo de Groot

FSI Amsterdam 2023



# Agenda

Enter your subtitle here

**1.0**

**VdS long history old sprinkler test**

1999 report

**1.1**

**Overview of standards**

Service & maintenance sprinkler test

**1.2**

**VdS 2091 test procedure**

Service & maintenance sprinkler test

**1.3**

**Five year test data from lab**

Sprinkler test per VdS 2091

**1.4**

**RTI Value**

Outcome sample test

**1.5**

**Consideration ESFR**

In process

**2.0**

**Sprinkler pipe inspection**

How does it look?

**3.0**

**About VdS Nederland**

Independent company

**3.1**

**How to contact**

Meet the team

# Disclaimer

This presentation contains potential fire protection related analyses for certain areas -industrial, commercial or residential facilities, any type of object / operation or product & system type- which may be exposed or part of a fire risk (analyze). Any data shared that could mistakenly be used to mitigate risks or failures shall be executed on a case-by-case basis considering local legislation, regulation, test protocols and/or standards and project-specific parameters; So far as VdS Netherlands, shown at the homepage ([www.vds-nederland.nl](http://www.vds-nederland.nl)) provide information free of charge, this is **done in good faith and without any liability.**

# Agenda item 1.0

# VdS long history

# VdS long history



VdS SCHADENVERHÜTUNG 

**Interne Mitteilung an die Technische Prüfstelle**  
Büro Darmstadt

erhalten Sie das beiliegende Ergebnisblatt.

**Ergebnis der Begutachtung der Stichprobe:**

Aufgrund der vorliegenden Stichprobe sind die zugrundegelegten Bedingungen zum Verbleib in der Anlage derzeit nicht erfüllt. Bitte informieren Sie den Betreiber / die Errichterfirma.  
Sollten Sie aufgrund des negativen Prüfungsergebnisses eine Erweiterung des Stichprobenumfangs um weitere 20 Sprinkler wünschen, so geben Sie bitte bei deren Übersendung die o.g. Prüfnummer an.

Die Prüfung wurde gemäß der derzeit gültigen Prüfanweisung Nr. WAL SP-AL für die Prüfung von Sprinklern aus Altanlagen durchgeführt.

Köln, 17.08.99  
Bch/PC



VdS SCHADENVERHÜTUNG 

**Sprinkler aus Altanlagen - Prüfungsergebnis SPA 99132**

Fehler 1: Versagen von Sprinklern:	Anzahl
Maximal zulässige Fehlerquote der 20 geprüften Sprinkler: 2,5%	
Keine Auslösung bei 1bar:	1 Stck.
K-Faktor bei 1bar um mehr als 30% reduziert:	0 Stck.
Keine Wasserverteilung bei 1bar:	0 Stck.
Ansprechtemperatur mehr als 20°C aus Toleranz:	0 Stck.
Fehlerquote:	5,0%
Ergebnis:	Negativ

Fehler 2: Eingeschränkte Funktion von Sprinklern:	Anzahl
Maximal zulässige Fehlerquote der 20 geprüften Sprinkler: 25%	
Auslösetemperatur außerhalb Toleranzfeld:	0 Stck.
Sprühbehinderungen bei 1bar:	0 Stck.
K-Faktor bei 1bar um mehr als 10% reduziert:	0 Stck.
Fehler aus 1:	1 Stck.
Fehlerquote:	5,0%
Ergebnis:	Positiv

**Bemerkungen:**  
Die Sprinkler waren äußerlich nur wenig verschmutzt. Ein Muster öffnete in der Funktionsprüfung nach dem Ansprechen des Auslöselements erst bei einem Druck von 3,5bar.

**Zulässige Fehlerquote:** Nicht eingehalten  
Köln, den 17.08.1999



# Why testing e.g. old sprinklers

How does it look?

K-factor reduction >10%



K-factor reduction >30%




K-factor reduction >30%



ESFR K25 (2002) dirt at sealing



Spray obstruction by sealing



Sealing assembly blocking



# Agenda item 1.1

## Overview of standards

# Overview of standards

## What to do?

### REQUIREMENTS FOR OLD SPRINKLER CHECK

DESCRIPTION	VDS 2091	TB80	FM 2-81	NFPA 25
<b>Initial sample size</b>	E.g. up to 5000spk / 20 samples.  Minimum 20 / building  A standard building of 18.000 m <sup>2</sup> = 1%	Minimum 4, or 1% per sprinkler type	xxx	Minimum 4, or 1% per object section
<b>Actions at the lab</b>	Visual assessment  a) 20% of the sprinklers (usually 4) test nominal response temperature  b) 80% percent of the sprinkler functional test	Per selected test protocol	xxx	Visual assessment, pass, then second test at the lab  a) Functional test at 0.5 bar  b) RTI testing  - SR sprinkler RTI ≤ 350  - QR sprinklers RTI ≤ 65  - ESFR sprinklers RTI ≤ 50

# Overview of standards

Then what?

## REQUIREMENTS FOR OLD SPRINKLER CHECK

DESCRIPTION	VDS2091	TB80	FM 2-81	NFPA 25
Interval	<ul style="list-style-type: none"> <li>- Generally every 25 years</li> <li>- Dry pendent in wet 12.5 years</li> <li>- Dry pendent in dry 6.25 years</li> <li>- Safety double sprinkler after 12.5 years</li> <li>- The sprinkler should be replaced after 50 years</li> </ul>	<ul style="list-style-type: none"> <li>- Replace or test every 50, or test continuing every 10 years.</li> <li>- Every 15 years via the pipe network inspection, visual check 5 sprinklers. If necessary replace or test.</li> </ul>	<ul style="list-style-type: none"> <li>- Fusible link &gt; 182°C, every 3 years</li> <li>- O-ring sprinklers, every 5 years</li> <li>- Dry type sprinklers, every 15 years. Replace all dry-type sprinkler before 2003</li> <li>- After fire, replace all non-operated sprinklers within a minimum of 6 m of any operated sprinklers</li> <li>- Conduct a physical and visual inspection of sealed concealed sprinklers. Physically minimum of 10% of the total number per room, and visually inspect all remaining sprinklers</li> </ul>	<ul style="list-style-type: none"> <li>- SR after 50 years, then every 10 years up to the year 75, from the year 75 every 5 years. (50-&gt;60-&gt;70-&gt;75-&gt;80-&gt;85...etc.)</li> <li>- QR &amp; ESFR after 20 years, then every 10 years up to 75 years, from 75 years every 5 years.</li> <li>- &gt; 163°C Fusible link every 5 years.</li> <li>- Dry sprinklers - after 15 years, further checks every 10 years</li> <li>- Listed corrosion resistant sprinklers in hostile environments, every 10 years. Non listed, every 5 years</li> </ul>
Then what	<p>The error rate possibly causing failure &gt; 2,5%</p> <p>The error rate possibly causing impairment &gt; 25</p> <p>The sum of both &gt; 25%</p> <p>Addition sample tests may be sensible otherwise replace all sprinklers</p>	<p>Test fails, replace all sprinklers or redo test with 4% of total installed</p>	<p>xxx</p>	<p>If one sprinkler does not meet requirement, all should be replaced</p>

# Overview of standards

## Test protocol reverence

### REQUIREMENTS FOR OLD SPRINKLER CHECK

DESCRIPTION	VDS 2091	TB80	FM 2-81	NFPA 25
<b>Standard reverence</b>	EN 12259-1, Annex B (temp)  EN 12259-1, Annex C (flow)  EN 12259-1, Annex E (function)	Depending on selected test standard	xxx	EN 12259-1, Annex E (0,5b function)  EN 12259-13, Annex G (ESFR @ RTI ≤ 50)  UL199

# Standard samples

## VdS 2091

### location & number samples

Total number of sprinklers	Number of sprinklers to be submitted
up to 5.000	20
up to 10.000	40
up to 20.000	60
up to 30.000	80

Sprinklers should mainly be taken from those areas in which operational influences may have caused damage to the sprinklers, e.g.:

- frequent change of water due to sprinkler system extensions;
- highly corrosive ambient conditions;
- influence of the water used;
- periodical temperature variations;
- vibrations;
- radiant heat.

Where the sprinklers are located in different buildings, at least 20 sprinklers per building shall be submitted.

In the case of different operational influences within one building it may be necessary to check a larger number of sprinklers. VdS will determine the number according to the hazard in question.

Additional measures shall be taken if

- the error rate possibly causing failure > 2,5%;
- the error rate possibly causing impairment > 25%;
- the sum of both > 25%.

VdS  
risk  
ers

## NFPA 25

### location & number of sample (location)

Examples of documents that can be used to determine the installation date include the Contractor's Material and Test Certificate for Aboveground Piping or the Certificate of Occupancy. Where documentation of the installation date is not available, the start date for the in-service performance testing interval should be based upon the sprinkler's manufacture date.

**A.5.3.1.1** Sprinklers should be first given a visual inspection in accordance with 5.2.1.1.1 to determine if replacement is required. Sprinklers that have passed the visual inspection should then be laboratory tested for sensitivity and functionality. The waterway should clear when sensitivity/functionality tested at 7 psi (0.5 bar) or the minimum listed operating pressure for dry sprinklers.

The thermal sensitivity should be such that the RTI does not exceed 350 (meters-seconds)<sup>1/2</sup> for standard-response sprinklers, 65 (meters-seconds)<sup>1/2</sup> for quick-response and residential sprinklers and 50 (meters-seconds)<sup>1/2</sup> for FSFR sprinklers

## TB80 5.13

### what to do with failures

Sprinklers, Ouder dan 50 jaar Testen of vervangen	<b>Basiseis</b> Sprinklers die ouder zijn dan 50 jaar moeten vervangen te worden.  <b>Alternatief</b> Als alternatief mag ook met een representatieve steekproef aangetoond worden dat de sprinklers nog goed functioneren. Deze steekproef moet dan wel elke 10 jaar herhaald te worden.  <b>Eisen aan de beproeving</b> In plaats van het vervangen van de sprinklers kan een representatieve steekproef worden genomen waarbij de geselcteerde sprinklers worden uitgenomen en beproefd. De steekproef moet bestaan uit ten minste vier sprinklers of 1% van de sprinklers (grootste waarde aanhouden) per sprinklertype uit elk gebied met gelijke omstandigheden.  De beproeving moet zijn afgestemd op sprinklers die in gebruik zijn geweest en moet bij voorkeur plaatsvinden op basis van de norm ten tijde van de aanleg of anders plaatsvinden aan de hand van de meest recente versie van EN 12259-1, UL 199 VdS 2091 of FM Approvals LLC Approval Standard Class Number 2000. Van de sprinklers moet het aanspreken, 'Thermal response' en 'Functional test', bij verschillende voordrukken worden beproefd waarna de waterdoorlaat (K-factor) moet worden gemeten.  Indien de sprinklers goedgekeurd zijn dan hoeven de sprinklers niet vervangen te worden.  Indien de sprinklers niet voldoen aan de eisen uit de onderhavige norm dan moet: c. de sprinklers vervangen worden of d. de steekproef vergroot (*) worden of e. middels een analyse aangetoond worden dat het blussysteem voldoet aan de vereiste functionaliteit.  <b>Opmerking (*)</b> De steekproef moet opnieuw uitgevoerd worden met ten minste twaalf sprinklers of 4 % van de sprinklers (grootste waarde aanhouden) per sprinklertype uit elk gebied met gelijke omstandigheden. Indien de sprinklers opnieuw niet voldoen dan moet: f. de sprinklers vervangen worden of g. middels een analyse aangetoond worden dat het blussysteem voldoet aan de vereiste functionaliteit.  De resultaten moeten in het logboek aanwezig zijn.
---	--

# Agenda item 1.2

# VdS 2109 test procedure

# VdS 2091 test procedure

## Sprinkler test


Additional measures shall be taken if:

the error rate possibly causing failure > 2,5% (5% or 3,25%)

the error rate possibly causing impairment > 25% (<50% or <35%);

the sum of both > 25% (<50% or 37.5%)

Fehler 1: Versagen von Sprinklern:	
Maximal zulässige Fehlerquote der 20 geprüften Sprinkler:	2,5%
Keine Auslösung bei 1bar:	1 Stck.
K-Faktor bei 1bar um mehr als 30% reduziert:	0 Stck.
Keine Wasserverteilung bei 1bar:	0 Stck.
Ansprechtemperatur mehr als 20°C aus Toleranz:	0 Stck.
Fehlerquote:	5,0%
Ergebnis:	Negativ
Fehler 2: Eingeschränkte Funktion von Sprinklern:	
Maximal zulässige Fehlerquote der 20 geprüften Sprinkler:	25%
Auslösetemperatur außerhalb Toleranzfeld:	0 Stck.
Sprühbehinderungen bei 1bar:	0 Stck.
K-Faktor bei 1bar um mehr als 10% reduziert:	0 Stck.
Fehler aus 1:	1 Stck.
Fehlerquote:	5,0%
Ergebnis:	Positiv
Bemerkungen:	
Die Sprinkler waren äußerlich nur wenig verschmutzt. Ein Muster öffnete in der Funktionsprüfung nach dem Ansprechen des Auslöselements erst bei einem Druck von 3,5bar.	



# Thresholds EN12259-1 Annex B

## Nominal operating temperature

Nominal operating temperature t [°C]	Calculation aid T	Threshold 1 <sup>1)</sup> [°C]	Threshold 2 <sup>2)</sup> [°C]	Threshold 3 <sup>3)</sup> [°C]	Threshold 4 <sup>3)</sup> [°C]
general <sup>1)</sup>	(0,035*t + 0,62)	(t - T - 20)	(t - T)	(t + T)	(t + T + 20)
71	3,105	47,8	67,8	74,2	94,2
74	3,210	50,7	70,7	77,3	97,3
100	4,120	75,8	95,8	104,2	124,2
104	4,260	79,7	99,7	108,3	128,3
138	5,450	112,5	132,5	143,5	163,5
141	5,555	115,4	135,4	146,6	166,6

<sup>1)</sup> nominal operating temperature t as per marking of sprinkler

<sup>2)</sup> rounded to one decimal place

<sup>3)</sup> rounded to one decimal place

Table A.3: Thresholds for tests of nominal operating temperature of fusible element sprinklers

Result	Result classification
Release below threshold 1	Failure
Release threshold 1 to below threshold 2	Impairment
Release threshold 2 to threshold 3	Function
Release above threshold 3 to threshold 4	Impairment
No release up to threshold 4	Failure

Table A.4: Classification of results

# Nominal operating temperature



# Tresholds EN12259-1 Annex B

## Functional test and test of water flow (K-factor)

Result from part 1	Result classification
No release	Failure
Water distribution impaired	Failure
K-factor from 0,35 bar $\geq$ 90% of nominal value, but water distribution impaired	Impairment
K-factor from 0,35 bar $\geq$ 90% of nominal value and water distribution not impaired	Function
K-factor at 0,35 bar $<$ 90% of nominal value	Classification as per part 2

**Table A.5:** Classification of the results from part 1

Result from part 2	Result classification
Water distribution prevented	Failure
Water distribution impaired	Impairment
K-factor at 1 bar $<$ 70% of nominal value	Failure
K-factor at 1 bar $<$ 90% of nominal value	Impairment
K-factor at the latest at 1 bar $\geq$ 90% of nominal value and water distribution not impaired	Function

**Table A.6:** Classification of results from part 2

*Note: If a sprinkler has faults of result classifications 'Failure' and 'Impairment', it will be classified as 'Failure'.*

# Agenda item 1.3

# Five year test data from lab

# Test result analyse

Both, impairment & failure = nicht bestanden



Batch test past 5 years

Pass / fail of batches

Batch analyse per activation element

Pass / fail of batches

Overview pass/fail past 5 years




# Test result analyze

Both, impairment & failure = nicht bestanden


Batch test per sprinkler position (value)

Batch per sprinkler position (%)




Batch test per system type (value)

Batch per system type (%)



# Test result analyze

Both, impairment & failure = nicht bestanden



# VdS 2091 test procedure, Netherlands

Both, impairment & failure = fail

All sprinkler test 2018 - 2022: 224 batches & 2105 sprinklers

	pass	fail	total
batches	69%	31%	100%
sprinkler	64%	36%	100%
lodge	spray	K-F >10 % red	K-F 30% red
3%	1%	57%	17%
			21%

Wet system 2018 - 2022: 174 batches & 1776 sprinklers

	pass	fail	total
batches	66%	34%	100%
sprinkler	62%	38%	100%
lodge	spray	K-F >10 % red	K-F 30% red
2%	1%	58%	18%
			22%

Dry pipe system 2018 - 2022: 29 batches & 156 sprinklers

	pass	fail	total
batches	86%	14%	100%
sprinkler	89%	11%	100%
lodge	spray	K-F >10 % red	K-F 30% red
0%	0%	63%	13%
			25%

Dry sprinkler 2018 - 2022: 49 batches & 242 sprinklers

	pass	fail	total
batches	76%	24%	100%
sprinkler	73%	27%	100%
lodge	spray	K-F >10 % red	K-F 30% red
3%	3%	50%	13%
			31%


- Lodge - Lodgment (closing part that gets stuck on the deflector)
- Spray - spray impedance (e.g. in the case of a damaged spray disc)
- K-F >10% red - K-Factor Reduced greater than 10%
- K-F 30% red - K-Factor Reduced greater than 30%
- Opening red - stuck cap (the cap prevents the flow of water)

# Agenda item 1.4

## RTI

# Response time index

EN12259-13, 4.15.1



$$RTI = \frac{-t_r (u)^{1/2}}{\ln \left[ 1 - \frac{\Delta T_b}{\Delta T_b / \Delta T_g} \right]}$$

$t_r$  = time van activation (seconds)

$U$  = actual air velocity test section of the duct,  $2.56 \pm 0.07$  m/s

$\Delta T_b$  = average sprinkler operating temperature minus the ambient temperature, in  $^{\circ}\text{C}$

$\Delta T_g$  = actual temperature of the gas ( $197^{\circ}\text{C}$ ) minus the ambient temperature, in  $^{\circ}\text{C}$ .

EN12259-13, 4.15.1

The conductivity (C factor) is set to zero. Because ESFR sprinklers are designed to operate quickly, the contribution of conductivity to overall sensitivity negligible.

# RTI results

## ESFR approval test

ESFR type @ lab	Metric K-factor	RTI-value $\sqrt{m*s}$ (excl. C-value)
K14 bulb 68°C @ VdS	202	26,7
K14 bulb 68°C @ Lab Y	202	24,1
K17 link 74°C @ VdS	242	27,0
K17 link 74°C @ Lab Y	242	31,2
K17 link 100°C @ VdS	242	28,0
K22 link 74°C @ VdS	323	28,0

Average: 27,5

# RTI results per EN 12259-13, 4.15.1

ESFR installed sprinkler

Type	Production year	Number	Plunge test air temp (°C)	Plunge test air velocity (m/s)	Activation (s)	RTI-value $\sqrt{m*s}$ (excl. C-value)
ESFR K360 74 °C	2002	1	197,3	2,57	4,9	23,3
		2	197,3	2,57	5,0	23,8
		3	197,5	2,55	5,7	27,1
		4	197,3	2,57	5,4	25,7
		5	197,2	2,55	4,1	19,4
		Nominal ->	197±6 °C	2,56±0,07m/s	Average->	23,9



# Agenda item 1.5

# Consideration ESFR

# VdS lab is planning to update ESFR old sprinkler test

---

Considerations: With (like NFPA) or without RTI test?

---

If testing RTI for ESFR, why not for any storage sprinkler?

---

Starting pressure at flow test: 0,5 bar (like NFPA) or take the lowest design pressure?

---

How many samples per batch?

---

So far, 80% of ESFR pass the functional test

---

# Agenda item 2.0

# Sprinkler pipe inspection


# Sprinkler pipe inspection: Why?

Pipes change on the inside



# Sprinkler pipe inspection: Why?

Pipes change on the inside




# Sprinkler pipe inspection: Why?


Pipes change on the inside

In open water (Rivers, ponds) → 100% sure to find sediment in de pipes

Dry pipe installations →



Sediment in Dry pipe cross mains



# Sprinkler pipe inspection: Why?

Wall thickness changes too



Micro organism



Typical air - water line



General Corrosion

# Agenda item 3.0

## About VdS Nederland

# VdS Nederland is NEN-EN-ISO 17020 Type A

**VdS Nederland inspect systems per  
NFPA, FM, VdS, CEA 4001, EN's**



**VdS** gebrand op brandveiligheid

**NEN-EN-ISO/IEC 17020 type A, RVA Accreditatie**

- \* Voor inspecties:
  - Blusschuiminstallaties
  - Sprinklerinstallaties
  - Blusgasinstallaties
  - Rookbeheersing
  - Brandmeldinstallaties
  - Ontruimingsinstallaties
- \* CCV inspectieschema
  - PGS
  - Vuurwerk
- \* Normconformiteit:
  - Oude sprinklersystemen
  - Zuurstofreductie



# Agenda item 3.1

## How to connect?

# Our inspectors are available, transparent & open

This is Leo 😊



# Visit our website for more information

[www.vds-nederland.nl](http://www.vds-nederland.nl) or [info@vds-Nederland.nl](mailto:info@vds-Nederland.nl)



## ONS TEAM

**Work hard. Play hard.**

Bij VdS Nederland geloven we in een goede informele werksfeer.

Er wordt door iedereen hard gewerkt, maar er is ook tijd om gezellig een praatje met elkaar te maken. Met een team op kantoor en een nog veel groter team van inspecteurs in de buitendienst werken we gezamenlijk aan de hoge kwaliteit die u van ons gewend bent.

### Team van Managers:

